

Barn with date 1843

This is a bank barn with rear entrance at upper level, in front a cart entrance with cow byre to the north of it retaining wooden skell booses; the barn is probably early 18th century but was given a round dressed stone arch and a date plaque in the 19th century. Considerable group value. Buildings attached in a poor way and roofless but ought not to be lost as they maintain the row of building. Yet another bank barn immediately next to Crooks Farm.

